:SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY ТО :BBO MASTER HONG KONG LTD. - MR. RICHARD HO C.C. ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

FACTORY AUDIT REPORT

APPLICANT : SAINSBURY'S SUPERMARKETS LTD. DATE : DEC. 16, 2004 NON FOODS 5/F 33 HOLBORN LONDON EC1N 2HT IJΚ ATTN.: RICHARD WARBEY

 Quality Systems Contract Control Design Control Incoming Goods & Mate Manufacturing Process Manufacturing Process Manufacturing Process Final Inspection, Pace Calibration Training & Quality And Housekeeping Environment Product Safety/Product Protection of Childred Health & Safety and Mate Equal Opportunities Freedom of Association Remuneration 	s Control s Inspection cking & Storage udit ct Testing en Working Conditions	Score (Min. 0/Max. 4) 2~3 3~4 3~4 3 3 3 2~3 1~2 2 3 Please refer to related section Please refer to related section
FACTORY NAME AND ADDRESS		DLD MANUFACTURING LIMITED L DEVELOPMENT ZONE, JIUJIANG, 2, CHINA
AUDITOR NAME	: AGI	
AUDIT DATE	: Dec. 08, 2004	
SCOPE OF AUDIT		acility and quality system of the on of disposable instant BBQ
SUMMARY	:	

Based upon the information acquired in the interview with the factory's representative, reviewing the records and the observations during the tour of the factory facilities, it is considered that the factory does have adequate facilities, manpower and quality system for producing the items. Some improvement should be made on those areas that are listed on the recommendation of this report.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

Supplier Audit Report

Date of visit	:	Dec. 08, 2004
Principle visit type	:	Announced Audit
Categories for visit	:	Vetting
Supplier Details		
Name	:	BBQ Master Hong Kong Limited
Address	:	Room 2003, 20/F, C.C. Wu Building, 302-308 Hennessy Road, Wanchai, Hong Kong
Telephone	:	852-25271125
Fax	:	852-25290470
Contact	:	Mr. Richard Ho (Position : Senior Manager)
Factory Details		
Name	:	ZHEN HUA FA HOUSEHOLD MANUFACTURING LIMITED
Address	:	1, LEKOU INDUSTRIAL DEVELOPMENT ZONE, JIUJIANG, NANHAI, FOSHAN CITY, CHINA
Telephone	:	86-757-86587283
Fax	:	86-757-86587583
Contact	:	Mr. Guan Ju Pei (Position : Manager)
Previous Assessments	:	0
Auditor Name ********************************	:	AGI ************************************

:SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY TO C.C. : BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081


Supplier Profile

Inception date of the factory	:	June, 2001
The factory is	:	Private
General information / history of the factory	:	The factory was established in June, 2001, it was a private company and the investor was from Hong Kong. They had set up the management system based on their experiences and products character. All of their products were exported to U.S.A and Europe markets.
Is there	:	 a) Production capability Yes b) Warehouse facilities Yes c) In-house design Yes d) Product development Yes e) On-site laboratory Yes
Product range	:	Charcoal briquets, instant light charcoal, disposable instant BBQ grill (The following products were found produced at the factory during our audit : Charcoal briquets)
Bought-in components	:	Coal, grill and packing materials
Major customers	:	Dollar general, K-mart, Supervalu, IGA, park'N shop, Mclane
Last year turnover	:	£ 3,000,000
Factory floor space (m^2)	:	20,000
Number of employees	:	137Management: 10Production: 100Quality: 5Design: 2Engineering: 10Others: 10
Hours worked per day	:	8 hours with 3 shift. Details of each -first shift 8:15 to 16:15 shift -second shift 16:15 to 0:15 -third shift 0:15 to 8:15
No. of day worked per week	:	6 days per week
Quality Manual available *********	: * * * *	No ************************************

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

Organization Chart Of Factory



TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

1) Quality Systems Score N/A Max Act 3 1.1 Is the quality system based on ISO 9000 or equivalent ? 4 1.2 Is there an independent Quality Department ? 4 4 Is there a management approved QA manual ? 4 1.3 0 Are personnel familiar with all relevant 4 1.4 4 instructions and quality procedures ? 1.5 Do products receive approval for quality before 4 4 being put into full scale production ? Do training records exist to show the skill 1.6 4 0 capabilities of all employees ? Total : 2.4 15 (62.5%)

Additional Comments

- The factory had set up the management system based on their experiences and production character.
- The documented procedures and work instructions of main processes and departments were available.
- The personnel interviewed were familiar with relevant procedures and instruction.
- The factory did not have quality manual and training record.

2) Contract Control

			Score		
		N/A	Max	Act	
2.1	Is there a written procedure for the control of vendors or sub-contractors ?		4	4	
2.2	Does a new vendor or sub-contractor receive formal approval from all relevant departments before an order is placed ?		4	3	
2.3	Are goods purchased to written specifications ?		4	4	
2.4	Are the specifications quoted on all relevant orders ?		4	2	
		Total :	16 (81	13 .3%)	

Additional Comments

The written procedure was available.

Before an order was placed, they would evaluate the suppliers based on production capacity, quality assurance, price and delivery schedule.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

```
NUMBER: IJ00120081
```

3) Design Control

		N/A	Sc Max	ore Act
3.1	Are procedures for control and verification of design established and maintained ?		4	3
3.2	Are design input requirements identified, documented and reviewed ?		4	3
3.3	Are design output documented and expressed in terms of requirements, calculations and analyses ?		4	3
3.4	Are verification procedures established and documented to ensure that design output meets design input requirements ?		4	3
3.5	Are procedures established and maintained to control change of design ?		4	3
		Total :	20 (75.	15 0%)

Additional Comments

The procedures were available, all designed new samples would be evaluated and approved by engineering dept., QC dept., production dept. and clients.

4) Incoming goods and Materials

			Score		
		N/A	Max	Act	
4.1	Are incoming goods inspected to drawings/ specifications?		4	3	
4.2	Are incoming goods supplied with the manufacturer's warranty ?	\checkmark			
4.3	Are certificates kept/recorded ?	\checkmark			
4.4	What degree of inspection is there ? (against sampling plan, or fix %)	\checkmark			
4.5	Are the results of inspections recorded ?		4	3	
4.6	Is material quarantined before release to production ?		4	2	
4.7	Is rejected material identified ?		4	2	
4.8	What action is taken on rejected raw material ?	\checkmark			
4.9	Is there an effective procedure for the control and rotation of accepted goods and materials, such as first in - first out ?		4	3	
		Total :	20	13	
			(65	.0%)	

Additional Comments

- For incoming coal, the IQC would randomly take samples to lab for physical testing.
- For other materials, the IQC would carry out random inspection according to approved samples and written specification.
- Inspection and test records were kept.

The results reflect our findings carried out at the particular point of time plus the specified place and the services rendered in relation to this report are subject to the terms and conditions of business of Intertek Testing Services HK Ltd.

~

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

5) Manufacturing Process Control

			Sc	ore
5.1	Are all work instruction available at each work	N/A	Max 4	Act 4
5.2	station ? Do instructions cover all important		4	3
5.3	characteristics ? Are obsolete work instruction removed from t	he	4	4
5.4	production area ? Are visual reference standards / samples used ?		4	3
5.5	Are they available and in good condition ?		4	4
5.6	Is product coding method implemented ?		4	0
5.7	Does the coding method provide sufficient information to identify the product rapidly ?	\checkmark		
5.8	Is scrap efficiently cleared from the shop floor ?		4	1
5.9	Are samples retained from each batch ?		4	3
5.10	Is there a separate area for rejected parts?		4	3
5.11	Is this area suitable ?	_	4	3
		Total :	40 (70	28 .0%)
5.12	Flow chart of the manufacturing process. Incoming coal — Grinding — Mixing — Forming Packing _ Delivery.		ing	

Additional Comments

- The main production activities in the factory were manufacture of charcoal briquettes.
- The factory did not implement product coding method.
- The floors of production areas were dirty and mess.
- 6) Manufacturing Process Inspection

			20	010
		N/A	Max	Act
6.1	Is quality monitored on all relevant line operations ?		4	3
6.2	Are inspectors independent of production ?		4	4
6.3	Are existing methods or tests adequate to detect non conformance and ensure effective control ?		4	3
5.4	Are defect classifications and acceptance tolerances clearly defined ?		4	3
б.5	Are inspection results recorded ?		4	3
6.6	Do the records provide effective traceability by identifying the process, line, machine, or operative ?		4	3
6.7	Are retention times of records specified ?		4	1
6.8	Are the inspection findings assessed to initiate meaningful corrective actions ?		4	3
5.9	Is there any evidence to show that corrective actions have been taken ?		4	3
		Total :	36	26
			(72	.2%)

Additional Comments

The patrol inspectors would check each process one time per one hour, moreover, inspection records were kept.

Score

The results reflect our findings carried out at the particular point of time plus the specified place and the services rendered in relation to this report are subject to the terms and conditions of business of Intertek Testing Services HK Ltd.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

Score

7) Final Inspection, Packing and Storage

			SCOLE		
		N/A	Max	Act	
7.1	Does the supplier carry out a statistical sampling method to check functionality and fitness for purpose ?		4	3	
7.2	Are the results of inspection kept ?		4	4	
7.3	Is non-conformance clearly isolated ?		4	3	
7.4	Does the supplier apply a method to trace back to the manufacturer ?		4	3	
7.5	Is there a written instruction for packaging and shipping requirement ?		4	4	
7.6	Is the storage area for finished goods adequate ?		4	3	
7.7	Is approval for shipping given by authorized personnel ?		4	3	
		Total :	28 (82	23 .1%)	

Additional Comments

Before shipment and after final packing, the designated persons would conduct random inspection according to approved samples and written specifications, moreover, physical tests (such as burning rate, moisture content, hardness and adhesive rate) would be carried out.

- Inspection and test records were kept.
- 8) <u>Calibration</u>

		N/A	Max	Act
8.1	Does precision inspection / testing equipment		4	3
	available adequately?			
8.2	Are gauges and test equipment adequate ?		4	3
8.3	How often is test equipment calibrated ?		4	0
8.4	Are records kept of these check ?	\checkmark		
8.5	Are the records traceable to national	\checkmark		
	standards ?			
	Tc	tal :	12	6
			(50	. 0왕)

Additional Comments

- The precision inspection / testing equipment is: Burning rate tester, moisture content meter, hardness tester and balances.
- Most of testing equipments were bought in recently and were available, but there was no plan to calibrate the equipments in the factory.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

9) Training and Internal Quality Audit

			Score		
		N/A	Max	Act	
9.1	Are procedures established for identifying training needs ?		4	3	
9.2	Are training records kept for all personnel directly involved with quality ?		4	0	
9.3	Are personnel adequately trained to perform specific assigned tasks affecting quality ?		4	3	
9.4	Are audits planned and documented ?		4	0	
9.5	Are audits conducted to verify compliance and effectiveness of quality system ?		4	0	
9.6	Are documented procedures established for governing audit activities ?		4	0	
		Total :	24	б	
			(25	.0%)	

Additional Comments

- No training record kept.
- There was no internal audit procedure and plan, moreover, the factory did not conduct internal audit.

10) Housekeeping

			Sac	ore	
		NT / N			
		N/A	Max	Act	
10.1	Is there any cleaning schedule for premises, equipment ?		4	1	
10.2	Is there any domestic animal in the factory ?		4	0	
10.3	Are procedures established in pest control ?		4	0	
10.4	Are the pesticides and baits used comply with any relevant national legislation ?	\checkmark			
10.5	Are the records kept for all pesticides and baits used ?	\checkmark			
10.6	Are the containers for material handling clean, hygienic and labelled ?		4	3	
10.7	Are lighting facilities adequate ?		4	3	
10.8	Is there a suitable area for 3 rd party inspection ?		4	3	
		Total :	24	10	
			(41.	.7%)	

Additional Comments

- Too many dusts and powders on the floors of production areas.

- The factory did not conduct pest control and no pest control procedure existed.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

```
NUMBER: IJ00120081
```

Score

11) Environment

12

	N/A	Max	Act
11.1 Does product / packaging highlight the proper		4	3
disposal procedure to maximise material life		_	-
cycles ?			
11.2 Are material sourcing programmes in operation		4	3
for recycling ?		т	J
		4	3
11.3 Are specific measures in place to minimise		4	3
atmospheric emissions (e.g. vapours, dust,			
etc.) or effluent ?			
11.4 Are environmental considerations used in vendor		4	2
analysis or choice of sub-contractors ?			
	Total :	16	11
		(68.	.75%)
Additional Comments			
- The factory had passed environment evaluations	carried out	by by	loca
government department, the certificate was kept.			
Product Safety/Product Testing			
12.1 Is the product required to comply with UK/Europea	n regulation	s ?	
	n regulation	s ?	
12.1 Is the product required to comply with UK/EuropeaNo information was given.	n regulation	s ?	
- No information was given.			ard 3
 No information was given. 12.2 Is the product covered by a specific European Saf 			ard 3
- No information was given.			ard a
 No information was given. 12.2 Is the product covered by a specific European Saf 		standa	ard ? ore
 No information was given. 12.2 Is the product covered by a specific European Saf 		standa	ore
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 	ety/Testing	standa Sc	ore Ac
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the 	ety/Testing	standa Sc Max	ore Act
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 	ety/Testing	standa Sc Max 4	ore Act 3
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent 	ety/Testing	standa Sc Max	ore Act 3
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent body ? 	ety/Testing N/A	standa Sc Max 4	ore Act
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent body ? 12.5 Which approvals bodies are used ? 	ety/Testing	standa Sc Max 4 4	ore Ac 3 4
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent body ? 12.5 Which approvals bodies are used ? 12.6 How often are products submitted for re-test ? 	ety/Testing N/A	standa Sc Max 4 4 4	ore Act 3 4
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent body ? 12.5 Which approvals bodies are used ? 12.6 How often are products submitted for re-test ? 12.7 Are precautions taken to ensure ongoing 	ety/Testing N/A	standa Sc Max 4 4	ore Ac 3 4
 No information was given. 12.2 Is the product covered by a specific European Saf No information was given. 12.3 Are tests conducted to ensure compliance to the standard / legislation ? 12.4 Are these tests conducted by an independent body ? 12.5 Which approvals bodies are used ? 12.6 How often are products submitted for re-test ? 	ety/Testing N/A	standa Sc Max 4 4 4	ore Ac 3 4

Total: 16 11 (68.75%)

Additional Comments

- The factory representative claimed that they would send the samples to independent lab for testing if clients required.
- During factory tour, we found a test report about "20lbs, charcoal briquettes" issued by MTL, the test result was "passed" and the report no. was "5503-304-0607".
- There was a lab in the factory, they could conduct some physical tests such as "burning rate, moisture content, hardness and adhesive test", there were qualified engineers to conduct these tests, moreover, records were kept completely.

The results reflect our findings carried out at the particular point of time plus the specified place and the services rendered in relation to this report are subject to the terms and conditions of business of Intertek Testing Services HK Ltd.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

13) Protection of Children

		Not assessed	Yes	No
13.1	Are policies and procedures documented for the employment of children?		\checkmark	
13.2	Are these policies written in appropriate languages?		\checkmark	
13.3	Are these policies understood by all employees?		\checkmark	
13.4	Are these policies available to employees for reference?		\checkmark	
13.5	Are there children / underage workers working at the facility?			\checkmark
13.6	Are procedures and documentation adequate to assure that no children will be employed?		\checkmark	
13.7	Is there any indication that young workers are exposed to dangerous, unsafe or unhealthy work conditions?			√
13.8	Are workstations suitable for young workers for purposes of safety?		\checkmark	
13.9	Do young workers understand safety instructions?		\checkmark	

factory is 18 years old.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

14) Health & Safety and Working Conditions Not Yes No assessed Are workers provided with a clean and safe work \checkmark 14.1 environment? Are there posted evacuation plans in local \checkmark 14.2 language and are they understood by all employees in case of fire or emergency? Are aisles clear of obstructions and are fire 14.3 doors accessible and unlocked? Are five exists clearly marked? 14.4 14.5 Does the employer make adequate on site first aid facilities and maintain a record of industrial accidents ? 14.6 Are precautions taken to protect workers at inherently dangerous work stations? Are appropriate five extinguishers available in 14.7 all area? 14.8 Does the employer safe guard personnel bv providing safety or protective equipment to maintain a safe working environment? 14.9 Are there adequate efforts made to control infestation problems at the work site? 14.10 Is adequate protection provided for employee use of toxic chemicals? 14.11 Are lighting condition acceptable? 14.12 Are electrical wiring properly installed and protected? 14.13 Are workers properly protected from noisy working environment and machines production high frequency? 14.14 Do employees acknowledge that they have received safety training by the company? Are records available to verify dates that safety 14.15 training was given with a list of employees in attendance? 14.16 Do all employees understand the safety signs that are posted in the workplace? Is safety training a part of new employee indoctrination? 14.17 Is safety training given to personnel upon reassignment to a new job or work situation? Are procedures in place to provide for detection 14.18 of potential health and safety threats to workers? 14.19 Are toilet facilities adequate in number for worker population?

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

14) Health & Safety and Working Conditions

		Not assessed	Yes	No
14.20	Are they reasonably accessible to the workers?		\checkmark	
14.21	Are workers able to use toilets as needed?		\checkmark	
14.22	Are toilet facilities functional, clean and sanitary in accordance with local customs?		\checkmark	
14.23	Do workers have access to potable water?		\checkmark	
	Is the supply of potable water sufficient to meet the needs of the worker population?		\checkmark	
14.25	If appropriate, are facilities adequate to store food in a sanitary fashion?	\checkmark		
14.26	Are dormitory facilities clean and sanitary, if provided?		\checkmark	
14.27	Do dormitory facilities provide adequate space for the number of occupants? (For Shenzhen area in China, the minimum space for each people should not be less than 2 square meter)		\checkmark	
14.28	Are toilet facilities available to dormitory occupants and are they clean and adequate?		\checkmark	
14.29 14.30			\checkmark	\checkmark
	Is the dormitory safe against the threat of fire?		\checkmark	

Additional Comments

Medical facility is provided.

- The details of medical facility is: There is a medical room in the factory, the designated person can treat some simple hurts and diseases, some usual medicines and medical tools were available. The charge of medical facilities is paid by the factory.
- Meal is not provided.
- The layout and ratio of toilet facilities to workers is : Toilet to person (8:1)/Basin to person (8:1).
- Too much dusts and powders on the floors of production areas.
- No safety training record kept.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

15) Equal Opportunities Not Yes No assessed Is the company policy clear in defining its \checkmark 15.1 tolerance of different religious beliefs, politics, sexual orientation and various affiliations? Is pay treatment of workers consistent with time \checkmark 15.2 in job and type of work? 15.3 Is there evidence that women are mistreated or \checkmark fired as a result of being pregnant? 15.4 Are there records of any unusual medical tests performed on women employees by the company? 15.5 Is there evidence of harassment in the workplace by signs or gestures of employees? \checkmark 15.6 Are training and pay opportunities equal among the sexes? 15.7 Do any employees claim to be affected by discriminatory practices? 15.8 Is there disparate treatment between union and non-union workers? 15.9 Is there any evidence of physical abuse of workers such as poor posture or scarred hands? 15.10 Is there any workers council to reflect workers' opinion to employers Additional Comments Nil. 16) Freedom of Association Not Ves NΟ assessed Does the company include the right to collective \checkmark 16.1 bargaining in its policies and procedures? \checkmark 16.2 Do employees acknowledge that they are free to bargain collectively?

- 16.3 Are there any indications of discrimination against those who have attempted to organize workers?
- 16.4 Is there any indication that forced labour is being employed?
- 16.5 Are there service contracts to explain the presence of armed guards?
- 16.6 Do workers have to place personal deposits with the company to work?
- 16.7 Is the first month wage held as security until worker leaves the company?

Additional Comments

— Nil.

The results reflect our findings carried out at the particular point of time plus the specified place and the services rendered in relation to this report are subject to the terms and conditions of business of Intertek Testing Services HK Ltd.

 \checkmark

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

```
NUMBER: IJ00120081
```

17)	Remune	ration	Not	Mar	NT-
			Not assessed	Yes	No
	17.1	Do pay records indicate that regular hours worked NOT exceed the legal requirement (40 hours per week, for China)?		\checkmark	
	17.2	Are workers allowed to work on a voluntary basis?		\checkmark	
	17.3 17.4	Are workers paid overtime for extra hours? Does overtime exceed the legal requirement? (In China, OT should not exceed 3 hours in a workday and not exceed 36 hours in a month)		\checkmark	\checkmark
	17.5	Is overtime remunerated at the premium rate? (For China, 1.5 times of the regular payment for normal working day; 2 times of the regular payment for rest day and 3 times of the regular payment for the legal holidays)		~	
	17.6	Do wages meet legal standards?		\checkmark	
	17.7	Are workers paid bonuses / incentives?		\checkmark	
	17.8	Are workers paid on a regular basis?		\checkmark	
	17.9	Are workers paid in a manner convenient to them?		\checkmark	
	17.10	Is there evidence that wages are reduced as a			\checkmark
		form of punishment or discrimination?		/	
		Are wages paid with sufficient explanation to ensure worker understanding?		√	
		Are pay stubs printed in the local language?		\checkmark	
	17.13	Are pay stubs given to the workers?		\checkmark	
	17.14	Is salary retained by employer?			\checkmark
		onal Comments .mum wage for the local area is : RMB 450.00			
18)	Recomm	endation			
10)		e factory should set up a complete quality manual.			
	– The	e factory should set up internal audit procedure, cernal audit.	plan and	d carry	out
		l training records should be kept.			
		l inspection and test equipments should be calibrat	ed on tim		dina
		calibration plan.		ie accur	arna

- The factory should conduct pest control.
- The floors of production areas should be tidy and clean.

TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

Factory profileFinished goods-charcoal briquettes
storage







TO :SAINSBURY'S SUPERMARKETS LTD. - RICHARD WARBEY C.C. :BBQ MASTER HONG KONG LTD. - MR. RICHARD HO ITS (LEICESTER) LTD. - PAUL RAYBOULD

NUMBER: IJ00120081

PHOTO ATTACHMENT:





